Release Notes

LANtools 10.94 RC2

Table of contents

02 **1. Preface**

03 **2. New features, improvements, and history**

03 LANconfig 10.94.0024 RC2 / LANmonitor 10.94.0007 RC2

04 LANconfig 10.94.0015 RC1 / LANmonitor 10.94.0005 RC1

05 **3. Important advice**

05 Disclaimer

1. Preface

The LANtools are a comprehensive set of free management & monitoring tools for a detailed configuration and monitoring of LANCOM devices.

This document describes the innovations within LANtools version 10.94 RC2, as well as the improvements since the previous version.

Note
LANCOM LANtools support Microsoft Windows 7, Windows 8, Windows 10, Windows 11, Windows 2008 Server, Windows Small Business Server 2011, Windows Server 2012, Windows Server 2012 R2, Windows Server 2016, and Windows Server 2019 (all 32- and 64-bit versions).

For Windows Vista and Windows 2008 Server you will find user data under \Users\USER\AppData\Roaming\LANCOM\ and the application files under \ProgramData\LANCOM\.

When upgrading to LANtools 8.50 or newer, all existing user- and application data is moved to the corresponding folders.

2. New features, improvements, and history

LANconfig 10.94.0024 RC2 / LANmonitor 10.94.0007 RC2

Bug fixes

LANconfig

→ On LANCOM devices with firmware lower than LCOS 10.50, reading the configuration via HTTPS failed.

→ In the ‘Interfaces / LAN / 802.1X Authenticator for ETH Ports’ dialog, the option to reference an existing RADIUS server was missing.

→ After activating the LANCOM Security Essentials Option, no corresponding action objects were created in the IPv4 firewall.

→ When the ‘Enforce device password policy’ option was enabled, it was not possible to create user accounts for additional administrators.
The user accounts of existing administrators could no longer be edited.

→ In the WireGuard peer configuration, it was not possible to enter a hyphen in the ‘Endpoint’ field.

→ The port speed ‘10 Mbps half duplex’ could not be set in the Ethernet port configuration.

LANconfig 10.94.0015 RC1 / LANmonitor 10.94.0005 RC1

New features

LANconfig / LANmonitor

→ Support for LCOS 10.94

3. Important advice

Disclaimer

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

LANCOM Systems GmbH
A Rohde & Schwarz Company
Adenauerstr. 20/B2
52146 Wuerselen | Germany
info@lancom.de | lancom-systems.com

LANCOM, LANCOM Systems, LCOS, LANcommunity, LANCOM Service LANcare, LANCOM Active Radio Control, and AirLancer are registered trademarks. All other names or descriptions used may be trademarks or registered trademarks of their owners. This document contains statements relating to future products and their attributes. LANCOM Systems reserves the right to change these without notice. No liability for technical errors and/or omissions. 11/2025